

Philco Radio & Television Corp.

Model: 38-7	Chassis:	Year: Pre October 1937
-------------	----------	------------------------

Power:	Circuit:	IF:
--------	----------	-----

Tubes:

Bands:

Resources

Riders Volume 9 - CHANGES 9-3

Riders Volume 8 - PHILCO 8-64

Riders Volume 8 - PHILCO 8-65

Riders Volume 8 - PHILCO 8-66

G.E. D-51, D-52

A switch is provided in these chassis which is used to cut it out a series audio coupling condenser between the plate of the B7 second detector-avc tube and the control grid of the 41 output tube. In most cases it has been found to allow this switch to remain closed all the time; therefore, its usefulness can be increased by making the following changes:

Disconnect the two wires connected to the switch, S2, in the schematic found on *RCA page 6-9* in *Rider's Volume VI*, and after soldering them together, tape them.

Connect a wire from the control grid cap connected to the B7 to one terminal of the switch. To the other terminal of S2, connect one side of a 0.0015-mf condenser and connect the other side of the condenser to the case of the receiver.

This procedure provides a point tone control which is extremely effective in reducing the tube hiss with weak signals. When the incoming signal is strong, the condenser may be switched out of the circuit, which gives the best fidelity. This type of tone control is more effective in reducing noise than the usual type of control connected across the output of the 41 power amplifier.

Motorola 5T-71A

The schematic for this chassis is the same as that shown on *page 3-7* in *Rider's Volume III* and on *page 1054* in the *Rider Combination Manual*, with the following changes:

The 0.25-megohm and 1-megohm resistors in series in the plate circuit of the third 24 r-f tube and the 0.1-mf bypass condenser from their junction have been replaced with a choke having the same parts number as the one shown in the grid circuit of the 171A output tube. This choke is connected directly between the plate of the 24 tube and the +B lead.

The choke in the grid circuit of the output tube has been replaced with a 0.2-megohm resistor.

Mid-West 7-36

As was noted on *page 7-2* in *Rider's Volume VII*, the tube complement of the late model of this receiver was changed, four metal tubes being employed. Below will find the voltage data for both the early and the late models.

Early 7-36						
	Plate	Screen	Cathode	Supp.	Grid	
12 R.F.	225	40	0	AVC		
12 C.	120					
58 Mixer	215	80		AVC		
58 1st Det.	215	80		AVC		
55 2nd Det.	215	80		AVC		
2A5 Output	215	345	0	0	17.5	
Rect.	240	200	0			
Plate voltage, 5.5						

Late 7-36						
	Plate	Screen	Cathode	Supp.	Cathode	
5K7 R.F.	225	100	0	0	0	
5K7 Mixer	225	100	0	0	0	
5K3 1st Det.	150	80	0	0	0	
5K3 2nd Det.	20	0	0	0	0	
42 Output	215	340	0	0		
30 Rect.	240	200	0			
Plate voltage, 5.5						

Arvin Chassis 518

In order to correct the calibration of the dial, the following procedure is to be used:

Rotate the dial pointer to .50 kc. Press with the thumb on the dial face above its center. Rotate the tuning knob while preventing the dial pointer from moving. This will enable the position of the dial pointer to be varied with respect to the tuning condenser and makes it possible to readjust the calibration without removing the chassis from its cabinet.

For other servicing data see pages 8-10, 8-12, and 8-13 in *Rider's Volume VIII*.

G.E. B-40

The schematic of this receiver, which is the same as RCA M-34, is shown on *RCA page 3-14* of *Rider's Volume III* and page 1854 of the *Rider Combination Manual*. The change explained below will increase the audio gain on medium and strong signals and also improve the A.V.C. action. The partial schematic shown here with are the original and revised circuits.

Interchange the connections at the terminal board of the red and green wires from the volume control. This places the grid coupling condenser in the circuit of the movable arm of the volume control. Then disconnect the green A.V.C. lead from the terminal board. (This lead is connected to the second terminal from the end on the bottom side of the terminal strip.) Solder a small 2-megohm resistor to this lead and solder the other end of the resistor to the lug on the terminal board to which the green lead from the volume control is attached.

Lafayette M-31 (1935)

Please make this change on the lower schematic on *Lafayette page 8-6* in *Rider's Volume VIII*: A connection should be made where the lead iron B+ crosses the lead from the plate of the 58. A jumper appears there in the schematic.

Philco 602

The tap between the voice coil and the hum bucking coil should be grounded to minimize hum. See schematic on *page 7-83* of *Rider's Volume VIII*.

The 133-15 ohms resistor, No. 36, has a part number 33-3235 instead of 33-3225.

Beginning with Run No. 3, the tuning condenser assembly was changed to a vernier type. The part number of this condenser, scale, and pointer remain the same.

The 1-megohm resistor, No. 40 had had a rating of $\frac{1}{2}$ watt. This should be replaced with a $\frac{1}{2}$ watt resistor of the same resistance value; the Part No. 33-510344.

Philco 270

Please make a note in your Index to *Rider's Manuals* that the parts list of Model 270 applies to the schematic of Model 270, found on *page 1-28* of the revised edition of *Rider's Volume I*; on *page 460-C* of the early edition; and on *page 1057* of the *Rider Combination Manual*.

Philco 116

A 50-mmf condenser has been added from the end terminal of condenser No. 63 (see schematic on *page 6-11* of *Rider's Volume VI*) to ground. This addition was made to prevent oscillation.

As of Run No. 14, the 1-megohm resistor, No. 81, has been changed from Part No. 4409 to 33-510344.

A change has been made in the design of the volume control, No. 66 on the schematic, the old part number was 33-5022 and this has been replaced with Part No. 33-5153.

The Model K-17 speaker, Part No. 36-1025, is used on the new Model 116-B. The cone assembly number is 02996; the field coil and pot assembly is 36-3104.

Philco 116X

The resistance of the field coil, No. 95 on the schematic shown on *page 6-13* of *Rider's Volume VI*, is shown as 1125 ohms. Change notes from the manufacturer state that this value is 1450 ohms.

The volume control No. 68 has been changed from Part No. 33-5110 to 33-5155.

Philco 1-F Transformers

The i-f transformers of several models have been changed and are listed below. In each case the new part number of the first i-f transformer is 32-2296 and that of the second i-f transformer is 32-2298.

Model	Part's List on Page	Rider's Volume
37-33	7-15	VII
37-34	8-17	VIII
37-38*	7-17	VII
37-623	7-55	VII
37-624	8-23	VIII

The second i-f transformer has a tertiary winding which is connected in series with the screen-grid circuit of the 1D5G i-f tube.

*In order to prevent oscillation in the i-f circuit of Model 37-38, a tubular condenser, Part No. 30-4020, 0.05 mf, is connected from the screens of the 1C7G detector-oscillator and the 1D5G i-f tubes to ground.

Philco 37-9, Code 121

Run No. 2. Condenser No. 35 has been changed from 16 mf to 18 mf, Part No. 30-2194.

To improve the operation of the i-f circuit, a 0.1-mf condenser, Part No. 30-4455, has been connected from the lead of the primary of the i-f transformer, No. 53, to ground.

To prevent distortion at minimum volume, the green-white wire connecting the center lug of the volume control, No. 67, to the automatic tuning dial a-f switch, No. 93, must be kept clear of the compensator, No. 54, and the diode circuit of the 6Q7G.

Run No. 3. Condensers 70 and 70A have been replaced by 8- and 10-mf condensers respectively, Part No. 30-2201. The 8-mf condenser, No. 72, has been replaced by a 18-mf condenser, Part No. 30-2200.

The schematic of this receiver will be found on *page 8-11* of *Rider's Volume VIII*. Note that the dial calibration notes of Model 37-10, see *page 8-15*, can be used for calibrating the dial of Model 37-9.

Philco 270

In order to reduce maximum volume buzz, the following parts were changed: the 1.17-ohm resistor, No. 22, was changed to 12.3 ohms; the 2-megohm resistor, No. 30, was changed to 4 megohms; and the 160,000-ohm resistor, No. 27, was changed to 240,000 ohms. See schematic on *page 8-75* of *Rider's Volume VIII*.

Philco 38-4, 38-5

When either of these models are operated on 25 cycles, a power transformer, Part No. 32-7598 must be employed. Also a 0.1-mf condenser must be connected across the speaker field coil, No. 65.

In order to reduce station rumble in the Model 38-4, the following parts were changed: the 0.01-mf condenser, No. 36, was changed to 0.0015 mf, and the 40,000-ohm resistor, No. 38, changed to 32,000 ohms.

In order to reduce frequency drift at the high-frequency end of the broadcast tuning range, in Run No. 3 the compensator No. 16, 1500 kc, Part No. 31-6196, was replaced with Part No. 31-6206, and two condensers, Part No. 30-1097, are connected in parallel with the new condenser. The range 1 oscillator transformer, No. 15, was changed from Part No. 32-2631 to 32-2894.

In Run No. 4 of 38-4 and Run No. 2 of 38-5, the 70,000-ohm resistor, No. 19, was changed to 51,000 ohms to improve the performance of the oscillator circuit on the short-wave bands. For schematic see *page 8-61* in *Rider's Volume VIII*.

Philco 38-7, Codes 121,124

Run No. 2. To provide uniform performance of the oscillator circuit, a 20-ohm resistor was connected in series with the cathode of the 6ASG detector-oscillator tube. See schematic on *page 8-65* of *Rider's Volume VIII*.

In order to reduce bass response, the following parts were changed in the Code 124 chassis:

Condenser, No. 24, was changed from 0.01 mf to 0.001 mf, Part No. 30-4201. Resistor, No. 32, was changed from 51,000 ohms to 40,000 ohms, Part No. 33-340339. Condenser, No. 35, was changed from 0.006 mf to 0.01 mf, Part No. 30-4479.

Run No. 3. To reduce frequency drift further at the high-frequency end of the broadcast range, the compensator, No. 7A, was replaced with Part No. 31-6206. Also a new thermal compensator was connected in parallel with compensator, No. 7A and mounted near resistor No. 12. The resistor is mounted in the chassis with a mounting clamp and an asbestos insulator. The resistor must be mounted like this or else the thermal compensator will not function properly.

Run No. 4. The thermal compensator added to the chassis in Run No. 3, was replaced by two fixed condensers, Part No. 30-1097.

Run No. 5. The 20-ohm resistor added in Run No. 2 was removed.

The part numbers of Nos. 26, 39, and 48 found in the list of parts on *page 8-65* are correct for Models 38-8 and 38-9. The correct part numbers for Model 38-7, both codes, follow:

No. 26, Volume Control, Part No. 33-5225; No. 39, Tone Control, Part No. 42-1347; and No. 48, Range Switch, Part No. 42-1339.

Philco 38-8, Code 121

Run No. 2. In order to increase the sensitivity of the shadowmeter, the following changes were made: Resistor, No. 12, was changed from 10,000 ohms to 13,000 ohms, Part No. 33-313639 and condenser, No. 17, was changed from 0.05 mf to 0.25 mf, Part No. 30-4134. See schematic on *page 8-65* of *Rider's Volume VIII*.

Run No. 3. To provide uniform performance of the oscillator circuit, a 20-ohm resistor was connected in series with the cathode of the 6ASG detector-oscillator tube.

Run No. 4. In order to increase the a-f response in the high frequencies, condenser No. 40, was changed from 0.008 mf to 0.004 mf, Part No. 30-4456.

Run No. 5. The 20-ohm resistor added in Run No. 3, was removed.

Philco 610

We have been advised by the manufacturer that the following changes should be made in the schematic numbers of this model found on *page 6-19* of *Rider's Volume VI*: the schematic number 54 should be changed to 41; No. 41 to 56; No. 56 to 54; No. 39 to 40; and No. 40 to 39. This will make the numbers of the wiring diagram, the base view, and the parts list agree.

Beginning with Run No. 15, the oscillator circuit of the second type of this chassis (see *page 7-87* of *Rider's Volume VII*) was changed to improve the oscillator action at 6.0 mc. Resistors No. 17 and No. 18 (51,000 ohms and 25,000 ohms) were removed. A 32,000-ohm resistor (Part No. 33-32133) was added from the switch terminal side of condenser No. 7 in the antenna circuit to ground. A 20-ohm resistor, Part No. 33-020133 was connected between the 6A7 cathode and ground.

MODELS 38-7(121,124)

38-8(121),38-9(121) PHILCO RADIO & TELEV. CORP.

Voltage, Trimmers, Chassis

PHILCO TUBES USED: Six—one 6A8G, det. osc.; one 6K7G, I. F. amp.; one 6J5G, 2nd Det. A. V. C.; one 6K5G 1st audio; one 6F6G, output; one 5Y4G rectifier.

CABINETS AND SPEAKERS:**Cabinet**

38-7 Code 121	XX
38-7 Code 121	T
38-7 Code 124	CS
38-8 Code 121	X
38-9 Code 121	K
38-9 Code 121	T
38-9 Code 121	X

Speaker

H31
K41
K41
HS
HS
S7
HS



**GLOWING BEAM INDICATOR**Fig. 6 Dial Calibration
Models 38-8; 38-9

Fig. 4—Locations of Compensators—Top of Chassis




Fig. 5 Dial Calibration
Model 38-7

Fig. 1—Socket Voltages—Underside of Chassis View
The voltages indicated by arrows were measured with a Philco 026 Circuit Tester which contains a sensitive voltmeter. Volume control at minimum, range switch in broadcast position, line voltage 115 A. C.

PHILCO RADIO & TELEV. CORP. MODELS 38-7(121,124)
38-8(121),38-9(121)

Schematic



©John F. Rider, Publisher

